

Sackville Street Piccadilly



Head Office:
Leigh House
7 Station Approach
Bexleyheath
Kent
DA7 4QP

T: 020 8304 3997

F: 020 8304 3996

E: enquiries@cdrestoration.co.uk

W: www.cdrestoration.co.uk



This street was built using the typical architectural styles of the early 1700's and in our opinion the building forming 6 – 8 Sackville Street is one of the best examples of skilled stonemasonry on display.

The building is currently being used for office space and C & D Restoration Limited was employed to restore the stonework to its original state using comparable specialist stone working skills.

All stone and brickwork was cleaned thoroughly using a fine nebulous cold water low pressure spray. Using non-vigorous, soft bristle brushes, stubborn stains (carbon deposits caused by pollution) were worked away. A jet wash was then used to remove all loose dirt and grime.

Defective natural stonework was then repaired using Portland limestone mix to match the existing lines, profiles, colour and texture of the stonework. Some of the glazed bricks were also replaced and re-grouted to complete the façade.

Stone fractures were treated by steel pinning and resin injection.

All cracked, loose and defective pointing from the stone and brickwork was raked out and re-pointed to match the existing style.

Not only has the work carried out restored the brick and stonework with respect to aesthetics, it has also prolonged the life of the building.



Federation
of Stone
Great Britain